

# **Product Change Notification**

PCN No: 2008-07-22-02 Report Date: July 22, 2008

Subject: GLK24064-25 PCB Rev 2.0

Firmware Version v5.9 Release

## **List of New / Changed Products:**

All of the following graphic displays (and their variants):

GLC24064 PCB Rev 2.0
GLK24064-25 PCB Rev 2.0
GLK240128-25 PCB Rev 1.1

### **Reason for Change:**

The recent change in the intelligence implementation of our GLK24064-25 has resulted in a lengthening of the keypad read delay to accommodate custom keypads.

# **Product Change:**

The following list of firmware changes is effective on all the variants of the graphic displays as stated under 'List of New / Changed Products'.

### Firmware Changes:

Display	New Firmware Version
GLC24064 PCB Rev 2.0	v5.9
GLK24064-25 PCB Rev 2.0	v5.9
GLK240128-25 PCB Rev 1.1	v5.9

# **New Released Firmware v5.9:**

1) A minimal delay of approximately 50us is added to each keypad read cycle to accommodate custom keypads of increased resistance.

# **Schedule of Change:**

August 1, 2008

### **Documentation Revision**

Revision	Changes	Date	Author
1.0	Initial Release	July 22, 2008	Clark

### **Contact Information:**

Clare Wagner (Sales Manager): <a href="mailto:cwagner@matrixorbital.ca">cwagner@matrixorbital.ca</a>

#### **Reference Documents/Attachments:**

Location: http://www.matrixorbital.ca/manuals/

## **Approvals:**

Engineering: James McTavish (Engineering Coordinator)

Sales: Clare Wagner (Sales Manager)

Production: Mike McTavish (Production Manager)